



Issuing Entity:
Larson International Inc.
P.O. Box 638
Plainview, TX 79073-0638
U.S.A.
Phone 806-293-1353
Fax 806-293-5215
www.larsonintl.com

Bulletin No.: L03-004
Release Date: 02/24/03
Effective Date: Immediately
Supercedes: N/A
Completion Date: N/A
Page: 1 of 1

SERVICE BULLETIN

Ride Manufacturer: Larson International Inc. **Affected Production Dates:** All

Ride Name: Fire Ball **Affected Serial Nos.:** All units

Abstract Of Issue:

Clarification of rider restrictions

Reason for Release:

Larson International Inc. has learned that some operators are not following proper guidelines for rider restrictions. This Bulletin is intended to clarify those issues.

Action To Be Taken:

Larson International Inc. requires all owner/operators of the above-named rides to enforce the following rider restrictions:

1. Each rider is to be at least 48" tall.
2. Patrons must be of the height, weight, and shape to properly fit in the passenger seats. The restraint system, including harness and seat belt, must properly and fully engage.
3. The patrons must have sufficient body strength and shoulders in order to maintain themselves in an upright position for the restraints to properly engage the patron and thighs capable of retaining the patron in the seat.